



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE # CQ-14-08

ISSUE DATE: November 21, 2014

LAST TIME BUY DATE: November 21, 2015

LAST TIME SHIP DATE: February 21, 2016

REASON FOR DISCONTINUANCE:

Manufacturing related issues requires IDT to discontinue the attached list of products.

Some of these products may have an alternate IDT part number as a drop in replacement or a suggested functional replacement.

Customer should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuation Notice. They may also contact their local IDT Sales Office listed on the IDT website at www.idt.com or the Marketing contact listed below. The affected parts lists show the applicable product marketing group.

Product Group Product Group Contact Information

MMT Victor Abarca (Victor.Abarca@idt.com) Phone# (408) 284-6578

SPO Carl May (Carl.May@idt.com) Phone (408) 284-2718

NET clocks@idt.com

PCS Libbie Nicholson-Kramer (Libbie.Nicholson-Kramer@idt.com) Phone (512) 312-4705

Last time buy orders may be submitted any time prior to the last time buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
1338C-31SRI	None	None	N/A	IDT Fab 4 Closed	MMT
1338C-31SRI8	None	None	N/A	IDT Fab 4 Closed	MMT
501A-DPK	None	None	N/A	Package Discontinued	MMT
501E-DPK	None	None	N/A	Package Discontinued	MMT
501E-DSW	None	None	N/A	Package Discontinued	MMT
5V49EE503-043NLGI	None	None	N/A	IDT Fab 4 Closed	MMT
5V49EE503-043NLGI8	None	None	N/A	IDT Fab 4 Closed	MMT
5V49EE701-029NDGI	None	None	N/A	IDT Fab 4 Closed	MMT
5V49EE701-029NDGI8	None	None	N/A	IDT Fab 4 Closed	MMT
6V49185PAG	None	None	N/A	IDT Fab 4 Closed	MMT
6V49185PAG8	None	None	N/A	IDT Fab 4 Closed	MMT
70V5378S100BCI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S100BCI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S100BGI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S100BGI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S133BCI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S133BCI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S133BGI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S133BGI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S166BCG	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S166BCG8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S166BGG	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S166BGG8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S200BGG	None	None	N/A	IDT Fab 4 Closed	SPO
70V5378S200BGG8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S100BC	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S100BC8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S100BCI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S100BCI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S133BC	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S133BC8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S133BCI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S133BCI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S166BC	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S166BC8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S166BCG	None	None	N/A	IDT Fab 4 Closed	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
70V5388S166BCGI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S166BCI	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S166BCI8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S200BC	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S200BC8	None	None	N/A	IDT Fab 4 Closed	SPO
70V5388S200BCG	None	None	N/A	IDT Fab 4 Closed	SPO
72103L35J8	None	None	N/A	IDT Fab 4 Closed	SPO
72103L35JI	None	None	N/A	IDT Fab 4 Closed	SPO
72103L50J8	None	None	N/A	IDT Fab 4 Closed	SPO
72104L35J8	None	None	N/A	IDT Fab 4 Closed	SPO
72104L50J8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10PF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10PFG	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10TF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10TFG	None	None	N/A	IDT Fab 4 Closed	SPO
72275L10TFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15PF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15TF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72275L15TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20TF	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72275L20TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L10PF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L10PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L10PFG	None	None	N/A	IDT Fab 4 Closed	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
72281L10PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L10TF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L10TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15PF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15TF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72281L15TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20TF	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72281L20TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10PF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10PFG	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10TF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L10TFG	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PFGI	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PFGI8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15TF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72285L15TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
72285L20PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20TF	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72285L20TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10PF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10PFG	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10TF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L10TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15PF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15TF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72291L15TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20PFI	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20TF	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20TF8	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20TFI	None	None	N/A	IDT Fab 4 Closed	SPO
72291L20TFI8	None	None	N/A	IDT Fab 4 Closed	SPO
723616L15PF	None	None	N/A	IDT Fab 4 Closed	SPO
723616L15PF8	None	None	N/A	IDT Fab 4 Closed	SPO
723616L15PFG	None	None	N/A	IDT Fab 4 Closed	SPO
723616L15PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
723616L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
723616L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
723616L20PFI	None	None	N/A	IDT Fab 4 Closed	SPO
723616L20PFI8	None	None	N/A	IDT Fab 4 Closed	SPO
723616L30PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72413L25D	None	None	N/A	IDT Fab 4 Closed	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
72413L25SO	None	None	N/A	IDT Fab 4 Closed	SPO
72413L25SO8	None	None	N/A	IDT Fab 4 Closed	SPO
72413L25SOG	None	None	N/A	IDT Fab 4 Closed	SPO
72413L25SOG8	None	None	N/A	IDT Fab 4 Closed	SPO
72413L35D	None	None	N/A	IDT Fab 4 Closed	SPO
72413L35SO	None	None	N/A	IDT Fab 4 Closed	SPO
72413L35SO8	None	None	N/A	IDT Fab 4 Closed	SPO
72413L45D	None	None	N/A	IDT Fab 4 Closed	SPO
72413L45SO	None	None	N/A	IDT Fab 4 Closed	SPO
72413L45SO8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20J	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20J8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20PFG	None	None	N/A	IDT Fab 4 Closed	SPO
72605L20PFG8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L25J	None	None	N/A	IDT Fab 4 Closed	SPO
72605L25J8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L25PF	None	None	N/A	IDT Fab 4 Closed	SPO
72605L25PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L35J	None	None	N/A	IDT Fab 4 Closed	SPO
72605L35J8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L35PF	None	None	N/A	IDT Fab 4 Closed	SPO
72605L35PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L50J	None	None	N/A	IDT Fab 4 Closed	SPO
72605L50J8	None	None	N/A	IDT Fab 4 Closed	SPO
72605L50PF	None	None	N/A	IDT Fab 4 Closed	SPO
72605L50PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20J	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20J8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20JG	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20JG8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20PF	None	None	N/A	IDT Fab 4 Closed	SPO
72615L20PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L25J	None	None	N/A	IDT Fab 4 Closed	SPO
72615L25J8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L25PF	None	None	N/A	IDT Fab 4 Closed	SPO
72615L25PF8	None	None	N/A	IDT Fab 4 Closed	SPO



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
72615L35J	None	None	N/A	IDT Fab 4 Closed	SPO
72615L35J8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L35PF	None	None	N/A	IDT Fab 4 Closed	SPO
72615L35PF8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L50J	None	None	N/A	IDT Fab 4 Closed	SPO
72615L50J8	None	None	N/A	IDT Fab 4 Closed	SPO
72615L50PF	None	None	N/A	IDT Fab 4 Closed	SPO
72615L50PF8	None	None	N/A	IDT Fab 4 Closed	SPO
9LRS4206AKLFT	None	None	N/A	IDT Fab 4 Closed	MMT
9LRS4228AKLFT	None	None	N/A	IDT Fab 4 Closed	MMT
9UMS9633BFW3LFT	None	None	N/A	IDT Fab 4 Closed	MMT
MK1714-01RLF	None	None	N/A	Discontinued Fab Base	MMT
MK1714-01RLFTR	None	None	N/A	Discontinued Fab Base	MMT
MK2732-06GLFTR	None	None	N/A	Discontinued Fab Base	MMT
MK3720DLF	None	None	N/A	Discontinued Fab Base	MMT
MK3720DLFTR	None	None	N/A	Discontinued Fab Base	MMT
MPC9109AC	83940DYL F		Now	Discontinued Fab Base	NET
MPC9109ACR2	83940DYL F		Now	Discontinued Fab Base	NET
MPC961CAC	None	None	N/A	Discontinued Fab Base	NET
MPC961CACR2	None	None	N/A	Discontinued Fab Base	NET
P95020NQG	None	None	N/A	Package Discontinued	PCS
P95020NQG8	None	None	N/A	Package Discontinued	PCS
P95021NQG	None	None	N/A	Package Discontinued	PCS
P95021NQG8	None	None	N/A	Package Discontinued	PCS

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[IDT \(Integrated Device Technology\):](#)

[70V5388S100BC](#) [70V5388S100BG](#) [70V5388S166BG8](#) [70V5388S166BC8](#) [70V5388S166BG](#) [70V5388S166BC](#)
[70V5388S200BG8](#) [70V5388S200BC8](#) [70V5388S133BG8](#) [70V5388S133BC8](#) [70V5388S100BG8](#) [70V5388S100BC8](#)
[70V5388S166BCI](#) [70V5388S166BGI](#) [70V5388S133BC](#) [70V5388S133BG](#) [70V5388S200BCG](#) [70V5388S200BG](#)
[70V5388S200BC](#) [70V5388S166BCI8](#) [70V5388S166BGI8](#)